






FIG. 4 PRIOR ART























FIG. 9








FIG. 10







BY DRAMAR 1.1






FIG. 13 PRIOR ART





FIG. 16B

RESISTANCE VARIATION OF VR1






FIG. 14





FIG. 15






FIG. 17






FIG. 18




TRACKING ERROR SIGNAL WWW - WWW - WWW

FIG. 19A



RESISTANCE VARIATION OF VR2

FIG. 19B



14/15






FIG. 20A








FIG. 21A




FIG. 21B